



FACILITY
ANALYSIS
SERVICES

Sample FAS Report

August 13, 2008

Actual Survey Date



A division of Luck Stone . 650 Peter Jefferson Parkway . Suite 300B . Charlottesville, VA 22911 . 1.877.442.7878 tel . 1.434.971.6995 fax . www.leetennis.com

TABLE OF CONTENTS

I.	Introduction _____	3
II.	Facility Information _____	3
III.	Historical Information _____	3
IV.	Court Analysis _____	4-19
V.	Maps - Current State / Desired State Drawings	
	Map 1 Topographical Perspective / Present state	22
	Map 1A Topographical Perspective / Desired state	23
	Map 1B Topographical Perspective / Desired Option 2	24
	Map 2 Drainage Perspective / Present state	25
	Map 3 3-Dimensional Perspective / Present state	26
	Map 4 Surface Thickness / Present state	28
	Map 4A Surface Thickness / Desired state	29
	Map 5 Irrigation System Perspective	30
VI.	Desired Maintenance _____	31-34
	A. Daily	
	B. Periodic	
	C. Annual	
	D. Tools & Equipment	
VII.	Recommendations & Conclusions _____	35-42
VIII.	5 Year Budget Maintenance Plan _____	43-44
VIX.	Court Correction Options _____	45
X.	ASBA Builders Specifications, Court re-conditioning & irrigation system specifications _____	46-54

I. Introduction

This tennis court survey was completed at the XXXXXXXXXXXXXXXX Club on XXXXXXXXXXXX. Ed Montecalvo, Consulting Services Manager and Roy Hey, Consulting Services for Lee Tennis Products conducted the survey and site analysis. XXXXXXXXXXXX, (cell phone number, XXX-XXX-XXXX), of XXXXXXXXXXXXXXXX Club requested the analysis. The club furnished some of the information in this report. The rest was obtained through personal observational research provided by Lee Tennis. All recommendations used herein are in accordance with the ASBA (American Sports Builders Association) formerly the United States Tennis Court and Track Builders Association specifications for tennis courts.

II. Facility Information

The 5 Har-Tru courts are located at, XXXXXXXX. XXXXXXXXXXX, XXXX, XXXXXXXXXXX, telephone XXX-XXX-XXXX. The club has approximately XXX active members. The tennis facility includes 5 Har-Tru courts laid out into one court battery which measures 274' x 126'. This facility also has one battery of 2 hard courts next to the Har-Tru clay courts. The Har-Tru courts sit on property located adjacent to the clubhouse. Some focused areas of improvement include, surface migration through wind and water drainage and drying of the surface during the afternoon.

III. Historical Information

The XXXXXXXXXXXXXXXX Club was built in 1926. The five Har-Tru clay courts have not experienced any major work or lifts.